

Display CARFAX in online listings:



Este reporte ha sido provisto sin cargo para usted por:

Autoway of Atlanta
712 Atlanta Hwy
Gainesville, GA 30501
(678) 696-8220



History-Based Value Report

History events affecting this vehicle's value



No Accidents Reported



Personal Vehicle



Open Recall

\$48,420 Retail Value

BLACKBOX AI



Vehicle History Report™

US \$44.99

2020 MERCEDES-BENZ GLE 350 4MATIC

VIN: 4JGFB4KB7LA217095
4 DOOR WAGON/SPORT UTILITY
2.0L I4 F DOHC 24V GASOLINE
ALL WHEEL DRIVE

This CARFAX Report Provided by:
Autoway of Atlanta



No se han reportado accidentes o daño a CARFAX



1 Registro del historial de mantenimiento



Por lo menos 1 orden de retiro



2 Dueños previos





Tipos de dueños: Arriendo personal, Personal



13,754 Última indicación del odómetro reportada


El CARFAX Vehicle History Report (reporte de historial de vehículo CARFAX) se basa únicamente en la información provista a CARFAX y disponible a partir 11/17/23 a las 9:51:45 AM (CST). Otros datos acerca de este vehículo, incluyendo problemas, podrían no haber sido informados a CARFAX. Utilice este reporte como una herramienta importante, junto con la inspección y conducción de prueba del vehículo, para tomar una mejor decisión en cuanto a la compra de su próximo automóvil usado.

 Historial de propietarios El número de propietarios es un estimado	Dueño 1	Dueño 2
Año de compra	2020	2022
Tipo de dueño	Arriendo personal	Personal
Tiempo estimado de posesión	1 año 5 meses	2 meses
En posesión en los estados/provincias siguientes	Ver Detalles	New York
Millas aprox. conducidas por año	3,850/año	---
Última indicación informada del odómetro	5,581	13,754

 Historial del título Carfax garantiza la información de esta sección.	Dueño 1	Dueño 2
Calificaciones de daños Salvamento Chatarra Reconstruido Incendio Inundación Granizo Defectuoso	<input checked="" type="checkbox"/> Garantizado Sin Problema	<input checked="" type="checkbox"/> Garantiz Sin Prob
Calificaciones de odómetro No Es Millaje Real Excede Límites Mecánicos	<input checked="" type="checkbox"/> Garantizado Sin Problema	<input checked="" type="checkbox"/> Garantiz Sin Prob




GARANTIZADO - El Departamento de Vehículos Motorizados (DMV) del Estado de EE. UU. no informó ninguno de estos problemas de título. Si descubre que un DMV informó alguno de estos problemas de título y no se incluyó en este informe, usted podría calificar.
Ver Términos | Ver Certificado


 Historial adicional No todos los accidentes / problemas se reportan a Carfax.	Dueño 1	Dueño 2
Pérdida Total No se reportan declaraciones de pérdida total a CARFAX.	<input checked="" type="checkbox"/> No Se Han Reportado Problemas	<input checked="" type="checkbox"/> No Se Han Reportado Problemas
Daño Estructural No hay daños estructurales reportados a CARFAX.	<input checked="" type="checkbox"/> No Se Han Reportado Problemas	<input checked="" type="checkbox"/> No Se Han Reportado Problemas
Activación de Bolsa de Aire No se ha informado a CARFAX de la activación de las bolsas de aire.	<input checked="" type="checkbox"/> No Se Han Reportado Problemas	<input checked="" type="checkbox"/> No Se Han Reportado Problemas
Revisión del odómetro No hay indicación de alteración del odómetro.	<input checked="" type="checkbox"/> No Se Han Indicado Problemas	<input checked="" type="checkbox"/> No Se Han Indicado Problemas

Accidente / Daño No hay accidentes o daños reportados a CARFAX.	No Se Han Reportado Problemas <input checked="" type="checkbox"/>	No Se Han Reportado Problemas <input checked="" type="checkbox"/>
Retirada del mercado por parte del fabricante Al menos 1 retirada del fabricante requiere reparación. La mayoría de las causas de retirada pueden ser reparadas gratuitamente.	Orden de Retiro Reportada	Orden de Retiro Reportada
Garantía Básica Se estima que le quedan 7 meses o 36,246 millas de garantía original. Confirmar con el distribuidor o el fabricante del vehículo.	Garantía Activa <input checked="" type="checkbox"/>	Garantía Activa <input checked="" type="checkbox"/>

CARFAX Historial Detallado





Dueño 1
Comprado: 2020



¡Bajo millaje! Este propietario condujo menos que el promedio en la industria de 15,000 millas por año.

Vehículo Arriendo Personal
3,850 mi/yr

Fecha	Millaje	Fuente	Observaciones
05/13/2020		Mercedes-Benz of Springfield Chicopee, MA 413-624-4100 mbspringfield.com ★ 4.7 / 5.0 353 Opiniones verificadas ❤️ 6,821 Preferido por los clientes	Vehicle offered for sale
05/28/2020	8	New York Inspection Station	Dealer had vehicle inspected to prepare it for sale - Passed safety inspection - Emissions inspection performed
05/29/2020		Silver Star Mercedes Benz Long Island City, NY 718-361-2332 silverstarny.com ★ 4.4 / 5.0 386 Opiniones verificadas ❤️ 7,678 Preferido por los clientes	Vehicle sold
05/29/2020		New York Motor Vehicle Dept. Brooklyn, NY	Registration issued or renewed - Passed safety inspection

<p>05/30/2020</p>	<p>Silver Star Mercedes Benz Long Island City, NY 718-361-2332 silverstarny.com</p> <p>★ 4.4 / 5.0 386 Opiniones verificadas</p> <p>♥ 7,678 Preferido por los clientes</p>	<p> Vehicle serviced</p> <ul style="list-style-type: none"> - Vehicle washed/detailed - Safety inspection performed
<p>06/23/2020</p>	<p>New York Motor Vehicle Dept.</p>	<p>Title issued or updated</p> <ul style="list-style-type: none"> - First owner reported - Loan or lien reported
<p>06/23/2020</p>	<p>Texas Motor Vehicle Dept. Roanoke, TX</p>	<p>Titled or registered as personal lease vehicle</p>
<p>12/11/2020</p>	<p>Mercedes-Benz USA LLC</p>	<p>Manufacturer Safety recall issued</p> <ul style="list-style-type: none"> - NHTSA #20V671 - Recall #2020110005 Recall - Safety Title/ Topic: Second Row Bench Middle Double Buckle MY: 2020-2021 Model(s): GLE-Clas - Status: Remedy Available <p>Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall</p> <p> Más información sobre esta retirada</p> <div data-bbox="142 1291 1481 1843" style="border: 1px solid blue; padding: 10px;"> <p>Description: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2020 - 2021 GLE-Class (167 platform) vehicles with 5 passenger seating, in certain circumstances while buckling the seatbelt, the middle seatbelt buckle could be pushed down into the gap below the seat cushion. If the passenger is not able to retrieve the buckle, the affected seat would not be available for an occupant to properly fasten the seatbelt. If a passenger does not fasten the seatbelt according to the Operator s Manual, the risk of injury in a crash could increase. An authorized Mercedes-Benz dealer will additionally secure of the middle seatbelt buckle on the affected vehicles to prevent it from being pushed below the seat cushion.</p> <p>If the passenger is not able to retrieve the buckle, the affected seat would not be available for an occupant to properly fasten the seatbelt. If a passenger does not fasten the seatbelt according to the Operator s Manual, the risk of injury in a crash could increase.</p> <p>Remedy: An authorized Mercedes-Benz dealer will additionally secure of the middle seatbelt buckle on the affected vehicles to prevent it from being pushed below the seat cushion.</p> </div>
<p>05/25/2021</p>	<p>Mercedes-Benz USA LLC</p>	<p>Manufacturer Safety recall issued</p> <ul style="list-style-type: none"> - NHTSA #21V354 - Recall #2021050012 - Status: Remedy Available

CARFAX BLACKBOX API

Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall




 **Más información sobre esta retirada**


Description: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2019 - 2021 CLA-Class (118 platform), GLE/GLS-Class (167 platform), A-Class (177 platform), E-Class (213 platform), E-Class Coupe/Convertible (238 platform), GLA/GLB-Class (247 platform), GLC-Class (253 platform), CLS-Class (257 platform), and AMG GT-Class 4-doors Coupe (290 platform) vehicles the MBUX multimedia system software might not meet specifications. Under very specific conditions, the MBUX multimedia system might not start and the display might remain black, or could reboot unintentionally after 50 seconds of initial startup. Accordingly, the rearview camera image might not be displayed or the display might be interrupted which could increase a risk of a crash or injury. Either an authorized Mercedes-Benz dealer or an over-the-air ("OTA") update will update the software of the communication module for the automatic emergency call system on the affected vehicles.

Under very specific conditions, the MBUX multimedia system might not start and the display might remain black, or could reboot unintentionally after 50 seconds of initial startup. Accordingly, the rearview camera image might not be displayed or the display might be interrupted which could increase a risk of a crash or injury.


Remedy: Either an authorized Mercedes-Benz dealer or an over-the-air ("OTA") update will update the software of the communication module for the automatic emergency call system on the affected vehicles.

BLACKBOX AI

06/05/2021	3,894	New York Inspection Station	Passed safety inspection - Emissions inspection performed
11/09/2021	5,581	Infiniti of Englewood Englewood, NJ	Vehicle offered for sale
11/19/2021		Mercedes-Benz of Nanuet Nanuet, NY 845-624-1500 nanuet.mercedesdealer.com	Vehicle offered for sale
		 4.8 / 5.0 457 Opiniones verificadas  11,264 Preferido por los clientes	
12/06/2021		INFINITI of Englewood Englewood, NJ 201-429-9805 infinitiofenglewood.com/	Vehicle sold
		 4.2 / 5.0 90 Opiniones verificadas	

 **879** Preferido por los clientes

12/07/2021	New Jersey Motor Vehicle Dept. Englewood, NJ Title #DA20213412422	Dealer took registration of this vehicle - Title issued or updated - Dealer took title of this vehicle while it was in inventory - Vehicle color noted as White
12/27/2021	New York Motor Vehicle Dept. Staten Island, NY	Registration issued or renewed - Passed safety inspection

 **Dueño 2**
Comprado: 2022 Vehículo Personal


Fecha	Millaje	Fuente	Observaciones
01/11/2022		New York Motor Vehicle Dept. Staten Island, NY	Title issued or updated - New owner reported
02/16/2022	11,620	New York Inspection Station	Passed safety inspection - Passed emissions inspection
03/21/2022	13,754	Auto Auction	Listed as a dealer vehicle - Vehicle sold



Millones de vehículos usados se compran y venden en subastas cada año.

BLACKBOX AI


03/21/2022 Rockland Motors
West Nyack, NY **Vehicle offered for sale**

 **3.9 / 5.0**
19 Opiniones verificadas

10/13/2022 Mercedes-Benz USA LLC **Manufacturer Safety recall issued**

- NHTSA #22V680
- Recall #2022090010 Recall - Safety Title/ Topic: Mounting of Rear Door Trim Bar MY: 2020-2022 Model(s): GLE-Class, GLS-C
- Status: Remedy Available

Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall

 **Más información sobre esta retirada**

Description: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2020-2022 GLE and GLS (167, X167 platform) vehicles, the fastening of the rear door window trim bars might not meet current production specifications. Under certain driving conditions, the trim bar might separate from the vehicle while driving. This might pose a risk of injury for other road users and increase the risk of a crash. An authorized Mercedes-Benz dealer will check the installation of the trim bars on the rear door windows and rework them, if necessary.

Under certain driving conditions, the trim bar might separate from the vehicle while driving. This might pose a risk of injury for other road users and increase the risk of a crash.

Remedy: An authorized Mercedes-Benz dealer will check the installation of the trim bars on the rear door windows and rework them, if necessary.

04/05/2023

Mercedes-Benz USA LLC

Manufacturer Safety recall issued

- NHTSA #23V177

- Recall #2023030014 Recall - Safety Title/ Topic: Check Installation of Air Conditioning Drain Hoses-2197592 MY: 2020-20

- Status: Remedy Available

Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall



Más información sobre esta retirada

SEE BLACKBOX FOR

Description: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2020-2021 GLE and GLS vehicles (167 platform), the air conditioning drain hoses might be incorrectly installed in the vehicle. In this case, condensation water from the air conditioning might enter the passenger compartment. If a significant volume of condensation water enters the driver and passenger side footwells, it might cause corrosion and/or short circuits to the electrical components installed in this area, which could increase the risk of fire. In addition, the performance of other features of the vehicle could be affected. For example, the automatic emergency call (eCall) might not be available, the vehicle might not be able to be unlocked and/or started; and the engine limp-home mode might be activated during driving, which could increase the risk of injury or a crash. An authorized Mercedes-Benz dealership will check the air conditioning drain hoses and correct their installation, if necessary.

If a significant volume of condensation water enters the driver and passenger side footwells, it might cause corrosion and/or short circuits to the electrical components installed in this area, which could increase the risk of fire. In addition, the performance of other features of the vehicle could be affected. For example, the automatic emergency call (eCall) might not be available, the vehicle might not be able to be unlocked and/or started; and the engine limp-home mode might be activated during driving, which could increase the risk of injury or a crash.

Remedy: An authorized Mercedes-Benz dealership will check the air conditioning drain hoses and correct their installation, if necessary.

¿Tiene preguntas? Clientes particulares, visiten nuestro Help Center (Centro de Ayuda) en www.carfax.com - En Inglés. Concesionarios o suscriptores, visiten nuestro Help Center (Centro de

Ayuda) en www.carfaxonline.com - En Inglés.



Glosario

Primer dueño

Cuando el o los primeros dueños de un vehículo obtienen un título del Department of Motor Vehicles (Departamento de vehículos motorizados) como prueba de propiedad.

Retiro por fabricante

Los fabricantes de automóviles emiten avisos de retiro del mercado para informar a los propietarios de vehículos de un defecto de seguridad o del incumplimiento de las normas federales mínimas de seguridad o de emisiones. Los retiros del fabricante se reparan sin costo alguno para el cliente.

Informe de nuevo dueño

Cuando un vehículo es vendido a un nuevo dueño, el título de propiedad del mismo deberá ser transferido al dueño o dueños nuevos en el Departamento de vehículos motorizados.

Historial de dueños

CARFAX define a un dueño como un individuo o negocio que posee y utiliza un vehículo. No todas las transacciones de títulos representan un cambio de dueño. Para estimar el número de dueños, CARFAX emplea tecnología propietaria que analiza todos los eventos del historial de un vehículo. El número estimado de dueños se encuentra disponible para los vehículos fabricados después de 1991, con títulos emitidos únicamente en los Estados Unidos, incluyendo Puerto Rico. Algunas veces los concesionarios optan por hacerse dueños legales de vehículos, y se exige que así lo hagan en los estados siguientes: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania y South Dakota. Tome esto en cuenta al examinar el historial estimado de dueños de un vehículo.

Título emitido

Un estado emite un título para proporcionarle al dueño prueba de propiedad. Cada título tiene su propio número. Cada título o matrícula que aparece registrado en el reporte CARFAX no necesariamente significa que ha habido cambio de dueño. En Canadá, la matrícula y factura de venta sirven como prueba de propiedad.

Síguenos:  facebook.com/CARFAX  [@CARFAXinc](https://twitter.com/CARFAXinc)  Acerca de CARFAX

CARFAX DEPENDE DE SUS FUENTES EN CUANTO A LA PRECISIÓN Y CONFIABILIDAD DE LA INFORMACIÓN QUE OFRECE. POR LO TANTO, CARFAX Y SUS AGENTES NO SE HACEN RESPONSABLES EN MODO ALGUNO POR LOS ERRORES U OMISIONES QUE HAYA EN ESTE REPORTE. CARFAX ADEMÁS DESCARGA EXPRESAMENTE TODA RESPONSABILIDAD DE GARANTÍAS, EXPRESAS O IMPLÍCITAS, INCLUYENDO LAS GARANTÍAS IMPLÍCITAS DE UTILIDAD COMERCIAL O IDONEIDAD PARA UN PROPÓSITO PARTICULAR.

© 2023 CARFAX, Inc., part of S&P Global. Reservados todos los derechos.
11/17/23 9:51:45 AM (CST)

He revisado y recibido una copia del Informe de Historial del Vehículo CARFAX para este vehículo 2020 MERCEDES-BENZ GLE (VIN: 4JGFB4KB7LA217095), el cual se basa sobre la información proporcionada a CARFAX disponible al 11/17/23 at 10:51 AM (EST).

Firma del cliente

Fecha

Firma del distribuidor

Fecha

CARFAX Warranty Check™

CARFAX has estimated the remaining original manufacturer warranty coverage based on information reported to us on this **2020 MERCEDES-BENZ GLE 350 4MATIC (4JGFB4KB7LA217095)**.

2020 MERCEDES-BENZ GLE 350 4MATIC

VIN: 4JGFB4KB7LA217095

Estimated start date of warranty: 05/29/2020


Last CARFAX reading reported on 03/21/2022: 13,754 miles

Today's Date: 11/17/2023

Type of Coverage	Original Warranty	Estimated Remaining Coverage
Basic	48 months or 50,000 miles	7 months or 36,246 miles
Drivetrain	48 months or 50,000 miles	7 months or 36,246 miles
Emissions	96 months or 80,000 miles	55 months or 66,246 miles
Corrosion	48 months or 50,000 miles	7 months or 36,246 miles
Transferable	No cost, unlimited owners covered	Same
Roadside	No data reported to CARFAX	
Safety belt & inflatable restraint	120 months or unlimited mileage	79 months or unlimited mileage
Specific Components	No data reported to CARFAX	

Notes
 Hybrid: Specific Components 8 year coverage. Emissions: Manufacturer covers emissions components under basic warranty. Emissions coverage may vary by state. Refer to owners manual for specific details.
 Transferable: No cost, unlimited owners covered. Roadside Assistance: Any vehicle with a Mercedes-Benz warranty is eligible. Safety Restraint: Safety belt coverage 10/Unlimited for new vehicles sold in the state of Kansas. Specific Components: Tires (except Sprinter/Metris), alignments and balancing, brake discs/pads, glass, wipers covered 1/12,000. Maintenance: Wear and tear items are not covered. Diesel: Sprinter 5/100,000.

BLACKBOX AI

 CARFAX Warranty Check provides an **estimate** of this vehicle's remaining warranty coverage. It does not take into account some vehicle history events such as some title brands that may void the original manufacturer warranty or ownership transfers that may decrease warranty coverage. This warranty information is only valid for vehicles manufactured for the United States. Complete warranty coverage information is available for this vehicle at the MERCEDES-BENZ website.

© 2023 CARFAX, Inc., part of S&P Global. Reservados todos los derechos.
11/17/23 9:51:45 AM (CST)

CARFAX Vehicle History Report Por Cortesía de:
Autoway of Atlanta



CARFAX Buyback Guarantee

Cobertura de la Garantía:

11/17/2023 - 11/17/2024

Descripción del Vehículo CARFAX:

2020 MERCEDES-BENZ GLE 350 4MATIC

VIN:
4JGFB4KB7LA217095

Estilo de Carrocería:
4 Door Wagon/Sport Utility

Línea de Mando:
All wheel drive

Motor:
2.0L I4 F DOHC 24V

Usted podría calificar

si descubre que el Departamento de Vehículos Motorizados de EE. UU. informó alguno de estos problemas de título y no se incluyó en este informe.



Daños Graves:

Salvamento/Chatarra
Vehículo Reconstruido
Desmantelado
Daños por
Incendio/Inundación/Granizo



Problemas con el Odómetro:

Excede Límites Mecánicos
No es Millaje Real



Historial de Vehículo Defectuoso:

Recompra por el Fabricante

Términos y Condiciones Vigentes

[View Terms and Conditions for CARFAX Buyback Guarantee coverage](#)